

Addendum 3

Trolley Rehab/Overhaul Project

RFB GM 02-15
(Replaces page 7)

1. PUBLIC ADDRESS SYSTEM

- a. The public address system that enables the driver to address passengers inside the trolley shall be tested and placed in working order.
- b. Inside speakers shall be replaced as needed with waterproof speakers.

Additional Items to be Considered and Incorporated in the Okaloosa County Trolley Rehab/Overhaul Estimate

1. Exterior wiring condition, exterior fuse box corrosion, electrical relay and electrical connector corrosion.
2. Electrical devices, including exterior lighting, horn flashers, etc., stop working without warning.
3. Re-engineer serpentine engine belt arrangement on bus 100. Belt will not stay in grooves as now situated.
4. Replace fuel tanks.
5. HVAC air distribution and volume for front windshield defrost and driver functions.
6. Replace rusty windshield wiper components.
7. Seals on roof top windows.
8. Front bumper corrosion.
9. Structural frame corrosion.
10. Corrosion on access doors and door frames on body.
11. Exterior paint.
12. Exterior decals.
13. Wheelchair lift functionality and safety features.
14. Body damage at lower front passenger entry door opening due to low ride height.
15. Exhaust outlet relocation.